Lead Service Line (LSL) Inventory

PWS ID (OR41#####)	41-93771
PWS name	Luckiamute Valley Charter Schools
Operator submitting report	Daniel Shimek
Date completed	9/24/24

Submit file to: DWP.DMCE@odhsoha.oregon.gov

color key	
Black - required	Lead
Green: OPTIONAL	0

Purple: calculated by spreadsheet - do not edit

	Required for Lead service line inventory			
Service line Site ID	Location Identifier (Required for Lead and GRR status only - optional for other service lines)	Service line current material	If galvanized, was upstream material ever lead?	Service line material identification method
Example:	123 Example Way	Non-lead - UNK - after 1985	No	Records only
	12975 Kings Valley Hwy. Monmouth OR97361	Non-lead - Copper	Unknown	On site inspection only
	12975 Kings Valley Hwy. Monmouth OR97361	Galvanized (Iron or Steel)	Unknown	On site inspection only